

Clearance Examination Preparation Instructions

Ohio Unleaded LLC conducts Clearance Examinations to determine whether a property meets applicable lead-safety requirements. Proper preparation is critical to avoid failed inspections, resampling, or additional fees.

PROPERTY CONDITION REQUIREMENTS

Before a Clearance Examination can be performed, all interior and exterior painted surfaces must be intact and free of deteriorated paint. This includes, but is not limited to:

- Walls, ceilings, and trim
- Doors and door frames
- Baseboards
- Windows and all window components, including sills, troughs, stops, jambs, and sashes
- Porches, stairs, railings, and exterior trim (if applicable)

Any chipping, peeling, cracking, or flaking paint must be properly corrected before scheduling a clearance exam.

If there is uncertainty regarding whether a surface will pass inspection, Ohio Unleaded LLC offers Paint Condition Assessments to identify areas of concern prior to scheduling.

REPAIR AND WORK PRACTICES

All paint disturbance should be completed using lead-safe work practices. At a *minimum*, Ohio Unleaded LLC strongly recommends that any repair work be completed by EPA Renovation, Repair, and Painting (RRP) certified workers.

When performing repairs:

- Use wet methods when scraping or sanding
- Contain work areas to prevent the spread of dust
- Cover floors and horizontal surfaces with disposable plastic
- Do not dry scrape or sand painted surfaces

After repairs are completed, work areas must be thoroughly cleaned before repainting.

CLEANING REQUIREMENTS PRIOR TO DUST WIPE SAMPLING

A Clearance Examination requires both a passing visual inspection and acceptable dust wipe results.

All areas must be free of visible dust and debris. Cleaning should always be performed from top to bottom.

Cleaning guidance includes:

- Window sills and troughs must be cleaned thoroughly using an all-purpose cleaner
- Wipe in one direction only; do not scrub back and forth
- Each window component should be cleaned at least twice
- Hard floors should be wet-mopped using clean water and a clean mop head for each room
- Carpeted floors should be vacuumed thoroughly; HEPA vacuums are strongly recommended

CLEARANCE EXAM DAY PREPARATION

On the day of the clearance examination:

- The property should be ready at least one hour prior to the scheduled appointment
- At least one window per room must be operable
- Furniture and personal items must be moved to allow access to floors, windows, and work areas

Last-minute cleaning immediately before sampling is not permitted and may result in rescheduling or failed results.

IMPORTANT NOTES

- Clearance results reflect property conditions at the time of inspection only
- Changes in conditions after inspection may result in future failures
- Ohio Unleaded LLC is not responsible for failed results due to inadequate preparation
- Ohio Unleaded LLC is not responsible for tenant-related delays or access issues

Following these instructions helps ensure a successful clearance examination and timely issuance of results.